

Weather Event Inspection

Site Name:	<u>Mixed Use Alameda Development</u> <u>6110 Alameda Blvd NE, Albuquerque, NM 87113</u>	Inspector:	Kyle Grinold
Permit #:	C18E086 NMR1001TQ NMR1001U5	Inspection Frequency:	
Date of Visit:	Oct 1, 2021, 1:55:40 PM	Last Rain Event Friday, October 1, 2021, 0.01"	Last Precipitation Saturday, October 2, 2021, 0.01" 48h Forecast 6% Chance of Rain

Part 1: Walk through the facility and look for signs of erosion control measures that may have failed or been damaged from the recent rainfall event.

a. Site Inspection

1. Are there any erosion control structures damaged from the rain event?

☒ Yes

☐ No

Notes:

Repair silt fence at west pond, approx. 100' Repair silt fence at the east lot. Approx. 80'.

2. Are there signs of new ruts or gullies from the rain event?

☐ Yes

☒ No

Notes:

N/A

3. Are there signs of significant amounts of mud in the street or outfalls from the rainfall event?

☐ Yes

☒ No

Notes:

N/A

4. Are there any conditions that need immediate attention?

☒ Yes

☐ No

Notes:

Fabric fence repair at the west pond and east dirt lot.

Part 2: Inspection report summary.

b. Inspection Report Summary

1. Qualifications of Inspector:

Training and work experience – see inspector qualification page in the SWPPP.

2. Measures/Areas Inspected:

Site Perimeter, Paved access points, Surrounding inlets, Outfalls, Ponds.

3. Observed Conditions:

Minor silt fence repairs required

4. Changes Necessary to the SWPPP:

NO changes to the SWPPP.

Weather Event Inspection

Site Name:	<u>Mixed Use Alameda Development</u> <u>6110 Alameda Blvd NE, Albuquerque, NM 87113</u>	Inspector:	Kyle Grinold
Permit #:	C18E086 NMR1001TQ NMR1001U5	Inspection Frequency:	
Date of Visit:	Oct 1, 2021, 1:55:40 PM	Last Rain Event Friday, October 1, 2021, 0.01"	Last Precipitation Saturday, October 2, 2021, 0.01" 48h Forecast 6% Chance of Rain

5. Were there any discharges?

☒ Yes ☐ No

Notes:

6. What did the water look like at the time of the discharge?

☐ Clear ☒ **Partly sandy**
☐ Very sandy

Notes:

7. Was Inspection Conducted Within 24 Hours of Last Rainfall Over 1/4"?

☒ Yes ☐ No

Notes:

8. How much did it rain?

Reference precipitation values included with this form.

Notes:

Certification & Signatures

Certification Statement:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Electronic Signature

X *Kyle Grinold*

Date
October 2, 2021 at 2:00:05 PM MDT



Title
Inspector



Weather Event Inspection

Site Name:	<u>Mixed Use Alameda Development</u> <u>6110 Alameda Blvd NE, Albuquerque, NM 87113</u>	Inspector:	Kyle Grinold		
Permit #:	C18E086 NMR1001TQ NMR1001U5	Inspection Frequency:			
Date of Visit:	Oct 1, 2021, 1:55:40 PM	Last Rain Event Friday, October 1, 2021, 0.01"		Last Precipitation Saturday, October 2, 2021, 0.01"	48h Forecast 6% Chance of Rain

Action Items

Title	Inspector	Date	Priority	Location	Description	Status	Closer	Notes	Imgs
 LATE BMP repair	Kyle Grinold	July 28, 2021	Immediate	See inspection	Silt fence repair.	Open			
 LATE BMP repair	Kyle Grinold	July 27, 2021	Immediate	South and north	Silt fence	Open			