

Weather Event Inspection				
Site Name:	<u>Mixed Use Alameda Development</u> 6110 Alameda Blvd NE, Albuquerque, NM 87113	Inspector:	Jeff Har	t
Permit #:	C18E086 NMR1001TQ NMR1001U5	Inspection Frequency:		
Date of Visit:	Jun 1, 2021, 4:39:41 PM	Last Rain Event Tuesday, June 1, 2021, 1.4"	Last Precipitation Tuesday, June 1, 2021, 1.4"	48h Forecast 19% Chance of Rain

Part 1: Walk through the facility and look for signs of erosion control measures that may have failed or been damaged from the recent rainfall event.

a. Site Inspection	
1. Are there any erosion control structures damaged from the rain event?	Yes No
Notes:	Repair silt fence at west pond, approx. 200' blown away from wood stakes. Repair silt fence at the east lot. Approx. 100'.
2. Are there signs of new ruts or gullies from the rain event?	Yes No
Notes:	N/A
3. Are there signs of significant amounts of mud in the street or outfalls from the rainfall event?	Yes No
Notes:	N/A
4. Are there any conditions that need immediate attention?	Yes No
Notes:	Fabric fence repair at the west pond and

## Part 2: Inspection report summary.

## b. Inspection Report Summary

1. Qualifications of Inspector:

Training and work experience â€" see inspector qualification page in the SWPPP.

2. Measures/Areas Inspected:

Site Perimeter, Paved access points, Surrounding inlets, Outfalls, Ponds.



Weather Event Inspection					
Site Name:	<u>Mixed Use Alameda Development</u> 6110 Alameda Blvd NE, Albuquerque, NM 87113	Inspector:	Jeff Har	t	
Permit #:	C18E086 NMR1001TQ NMR1001U5	Inspection Frequency:			
Date of Visit:	Jun 1, 2021, 4:39:41 PM	Last Rain Event Tuesday, June 1, 2021, 1.4"	Last Precipitation Tuesday, June 1, 2021, 1.4"	48h Forecast 19% Chance of Rain	

3. Observed Conditions:	
	Minor silt fence repairs required. Sediment escaped from north lot to the SW corner and sidewalk.
4. Changes Necessary to the SWPPP:	NO changes to the SWPPP.
5. Were there any discharges?	Yes No
Notes:	Sediment escaped from north lot to the SW corner and sidewalk. Designated ponding.
6. What did the water look like at the time of the discharge?	Clear Partly sandy
	<b>✓</b> Very sandy
Notes:	N/A
7. Was Inspection Conducted Within 24 Hours of Last Rainfall Over	Yes No
1/4"?	
1/4"? Notes:	Weather Event 05/31/21= 1.40" per NOAA weather mapping at the time of inspection.
	weather mapping at the time of
Notes:	weather mapping at the time of
	140



Weather Event Inspection					
Site Name:	<u>Mixed Use Alameda Development</u> 6110 Alameda Blvd NE, Albuquerque, NM 87113	Inspector:	Jeff Har	t	
Permit #:	C18E086 NMR1001TQ NMR1001U5	Inspection Frequency:			
Date of Visit:	Jun 1, 2021, 4:39:41 PM	Last Rain Event Tuesday, June 1, 2021, 1.4"	Last Precipitation Tuesday, June 1, 2021, 1.4"	48h Forecast 19% Chance of Rain	

## Certification & Signatures

## Certification Statement:

 $\hat{a} \in \mathbb{C}$  certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. $\hat{a} \in \mathbb{D}$ 

**Electronic Signature** 

X Jeff Hart	Date	
A Jejj Hart	June 1, 2021 at 4:41:31 PM MDT	

Title Senior Inspector



Weather Event Inspection					
Site Name:	<u>Mixed Use Alameda Development</u> <u>6110 Alameda Blvd NE, Albuquerque, NM 87113</u>	Inspector:	Jeff Har	t	
Permit #:	C18E086 NMR1001TQ NMR1001U5	Inspection Frequency:			
Date of Visit:	Jun 1, 2021, 4:39:41 PM	Last Rain Event Tuesday, June 1, 2021, 1.4"	Last Precipitation Tuesday, June 1, 2021, 1.4"	48h Forecast 19% Chance of Rain	

There Are No Action Items