

## City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:		Alameda Crossing (f.k.a. Campo del Norte)					
Location:		ESC File No.		NPDES Id. No.			
Site Contact Name & Agency	Chris Montoya - Pulte		Phone: (o)				
	<a href="mailto:Christopher.Montoya@PulteGroup.com">Christopher.Montoya@PulteGroup.com</a>		Phone: (m)		505-277-7727		
Owner	Pulte Homes		Phone: (o)				
Owner's e-mail			Phone: (m)				
Inspection Date:	09/11/20	Start/End Time:	0945/1030hrs				
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:		home construction					
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	x	Follow Up	

Weather at time of inspection?	Partly Cloudy	Temperature: ~	57*
Estimated date of last storm 0.25" or greater	8/31/2020		

Item Number	Deficiency/ Corrective Action		
1	Sediment BMP or stabilization of soil north of property line and curb line of Alameda		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes:	Inspection conducted adhering to Covid-19 constraints

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 09/11/20