



## City of Albuquerque Stormwater Construction Site Inspection Report

### General Information

Project Name:	Alameda Crossing (f.k.a. Campo del Norte)		
Location:		ESC File No.	NPDES Id. No.
Site Contact Name & Agency	Chris Montoya - Pulte	Phone: (o)	
Owner	<a href="mailto:Christopher.Montoya@PulteGroup.com">Christopher.Montoya@PulteGroup.com</a>	Phone: (m)	505-277-7727
Owner's e-mail	Pulte Homes	Phone: (o)	
Inspection Date:	11/10/20	Start/End Time:	7am
CoA Stormwater Inspector:	Doug Hughes		
Construction Phase:	home construction		
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input checked="" type="checkbox"/> 311/Complaint <input checked="" type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	30
Estimated date of last storm 0.25" or greater	10/27/2020		

Item Number	Deficiency/ Corrective Action		
1	NPDES not Posted for public viewing		
2	Self-Inspection reports not provided		
3	SWPPP Stormwater team not provided		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 6/11/2020

Notes:	Inspection conducted adhering to Covid-19 constraints

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Doug Hughes - 924-3420  
[jhughes@cabq.gov](mailto:jhughes@cabq.gov) 11/10/20