



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Alameda Crossing (Campo del Norte)		
Location:	alameda and louisiana		
Site Contact Name & Agency	Troy Crutchfield - Pulte	ESC File No.	C18E102
	troy.crutchfield2@pulte.com	NPDES Id. No.	NMR100LO
Inspection Date:	07/23/19	Start/End Time:	0730/0800hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	home construction		
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☒ 311/Complaint ☒ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	71*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
1	Washout at washout facility. Have trades utilize provided washout facility		
2	Waste not in acceptable container. Please clean waste outside perimeter walls-Alameda & Signal		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 7/8/2019

Notes:	28 photos on this inspection of issues.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 07/23/19