



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Alameda Crossing (Campo del Norte)				
Location:	alameda and louisiana				
Site Contact Name & Agency	Troy Crutchfield - Pulte	ESC File No.	C18E102		
	troy.crutchfield2@pulte.com	NPDES Id. No.	NMR100LO		
Inspection Date:	09/16/19	Start/End Time:	0800/0830hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	home construction				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	65*
Estimated date of last storm 0.25" or greater	9/15/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 09/02/19 on site

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 09/16/19