

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:		Campo Del Norte					
Location:		Alameda and Signal					
Site Contact Name & Agency	Dan Mallak			ESC File No.		C18E102	
	Pulte Homes			NPDES Id. No.		NMR1001LO	
Inspection Date:		06/07/19	Start/End Time:		10:00	10:30	
CoA Stormwater Inspector:			Curtis Cherne				
Construction Phase:		constructing walls, some pads poured					
Type of Inspection:	X	Regular		Storm Event		Post Storm Event >0.25"	
						311/Complaint	Follow Up

Weather at time of inspection?	Clear	Temperature: ~	60
Estimated date of last storm 0.25" or greater	5/10/2019		

Item Number	Deficiency/ Corrective Action			
	none			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	request	Latest report Date:	11/12/2018

Notes:	
Site was very clean	
Walked site with Dan and Nick	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Curtis Cherne PE, 505-924-3420
ccherne@cabq.gov 06/07/2024

06/07/19

Autochrome