

# CITY OF ALBUQUERQUE



July 23, 2019

Dan Mallak, Pulte Group of New Mexico, [dan.mallak@pulte.com](mailto:dan.mallak@pulte.com)  
Troy Crutchfield, Pulte Group of New Mexico, [troy.Crutchfield2@pulte.com](mailto:troy.Crutchfield2@pulte.com)

Copy: Kevin Patton, Pulte Group of New Mexico, [kevin.patton@pultegroup.com](mailto:kevin.patton@pultegroup.com)  
Tim Slatunas, Green Globe Environmental, [tim@greenglobenm.com](mailto:tim@greenglobenm.com)

Site: Campo Del Norte/Alameda Crossing

**Re: Drainage Ordinance (14-5-2-1) Violations for Construction Site Waste(s)**

Dear Mr. Mallak and Mr. Crutchfield,

The following violations were observed at today's inspection.

1. Construction and domestic waste not in an acceptable container.
2. Wash-out not in an acceptable wash-out facility.

Some of the photos are shown below:

PO Box 1293

Albuquerque

NM 87103

[www.cabq.gov](http://www.cabq.gov)



Domestic waste not in an acceptable container.





PO Box 1293

Construction and domestic waste not in an acceptable container.

Albuquerque

NM 87103

[www.cabq.gov](http://www.cabq.gov)



Wash-out on the ground.

**Required Mitigation:**

1. Place construction and domestic waste in an acceptable container.
2. Remove all wash-outs from the ground and dispose of properly. Have workers use an acceptable wash-out facility in the future.

If violations are not mitigated within 7 days, the property owner is subject to a fine of \$500/day per the City's Drainage Control Ordinance.

If you would like to schedule a follow-up inspection at a day and time of your convenience, prior to 7 days from the date of this letter please let me know.

If you have any questions, you can contact me at 924-3420.

Sincerely,

Curtis Cherne, P.E.  
Principal Engineer, Stormwater Quality  
Planning Dept.

PO Box 1293

Albuquerque

NM 87103

[www.cabq.gov](http://www.cabq.gov)