
PROPRIETARY COMPANY MATERIAL



PulteGroup

Date & Time : 05-14-2020 at 1:44 PM

NATIONAL STORM WATER QUALITY PROGRAM SITE INSPECTION REPORT (SIR)

			For use on most Pulte	Group Sites as of 01/01/2016				
Commun	ity Name:	Pulte: Campo Del Nor	e, Albuquerque, NM 87113 NPI	DES: NMR1001LO				
		(Include Site Name, Ci	ty, State, Zip Code and NPDES/0	Construction Storm Water Perm	it Number)			
Master S	ite List ID:	1261	Ins	spection performed by: Mario A	lderete, CESSWI CISEC, Green	Globe Environmental		
				(Print Na	ame, Company, and Title / Qual	ifications)		
Stages o	f Construction:	(check all that apply)	Land Development	Inactive	Vertical Construction	Post-Construction		
Type of I	Inspection:	(check all that apply)	Routine Inspection	Storm-Event Related	Final Site Inspection			
I.	SWPPP - Respond	to all Questions						
Item	o miri inspond				Yes	No		
A	Was the SWPPP acces	sible at the time of the inspect	ion?	?		If "No," then an Action		
В		identified in the SWPPP?				Item is required.		
C	=	ect the current stage of develop	ment?			Describe all Action Items		
D		0 1			X	on the reverse side of this		
Е	Was the SWPPP accessible at the time of the inspection? If "No," then an Item is requi Is the SSWR correctly identified in the SWPPP? Image: Construction of the inspection of the inspection of the is required. Does the SWPPP reflect the current stage of development? Image: Construction of the inspection of the reverse side is needed. Have all SIR action Items identified on the preceding reports been resolved? Image: Construction of the reverse side is needed. Is NSQP Signage posted and in compliance with NSQP requirements? Image: Construction of the reverse side is needed.							
II.		-	at triggered an Inspection:11	-21-2019				
Provide rainfall information as required by the Applicable Permit: <u>1 inch</u> (Base on the storm-event related l								
					Frequency	required by the Applicable Permit)		
III.	Site BMP Inspectio	n	Not					
<u>Item</u>	SWPPP Items		<u>Applicable</u>	<u>Acceptable</u>	Action Item	Assigned To		
Erosion	Control							
1	Protection of Disturb	ed Areas	\boxtimes					
2	Slope Protection		\boxtimes					
3	Vegetation / Revegeta	ation	\boxtimes					
4	Velocity Reduction D	Devices / Outlet Protection		\boxtimes	\Box .			
Sedime	nt Control							
5	Check Dams (rock, gr	avel, other)		\boxtimes				
6	Silt Fence			\boxtimes				
7	Berms, Dikes, Straw V	Wattles	\boxtimes					
8	Detention Basins/Sed	liment Traps						
9	Stockpiles Protected/	Stabilized	\boxtimes					
10	Storm Water Inlet Pro	tection		\boxtimes				
Housek	eeping / Trade Comp	oliance						
11	Waste and Trash Man	agement			\boxtimes .			
12	Spill and Leak Preven	ition		\boxtimes				
13	Sanitary Stations			\boxtimes				
14	Concrete and Constru	ction Washouts			\boxtimes .			
15	Material Use and Pote	ential Contaminate Storage			\Box .			
16	Equipment Storage ar	nd Maintenance	\boxtimes		\Box .			
17	Construction Exits ar	nd Entrances		\boxtimes				
18	Dust Control			\boxtimes	□ .			
19	Street Sweeping			\boxtimes	Ľ.			

PROPRIETARY COMPANY MATERIAL

		INOL					
<u>Item</u>	SWPPP Items (continued)	<u>Applicable</u>	<u>Acceptable</u>	Action Item	Assign	ed To	
Other							
20	Non-Storm Water Flow		\boxtimes				
21	Site's Weathering of Storm Events						
22	Site Discharge Points						
23	BMP Provider Performance		\boxtimes				
IV.	Action Items			V. Responsive Action Completion			
Item	Location and Responsive Action to be taken			Date Noted	Date of Completion	Initials	
11	Deficiency Name: 8700 la pradera Corrective Action: Clean and contain trash in the lot			05-07-2020			
14	Deficiency Name: 6305 Alpenglow Corrective Action: Remove and clean concrete washout			05-07-2020			
14	Deficiency Name: 6313 Alpenglow Corrective Action: Remove and clean concrete washout			05-07-2020			

Attach additional sheet(s) of SIR addendum if necessary

SIR must be reviewed and signed below by SSWR - Not Delegable: I certify under penalty of law that Sections I-V of this document and all attachments were prepared by me or under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. In the event there are no Action Items in this report that have remained unresolved for a period in excess of that allowed by the Applicable Construction General Permit, I further certify under penalty of law that this Site is in compliance with the SWPPP and the Applicable Construction General Permit. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment for knowing violations. Certification applies to the area under the supervision of the SSWR signing this report.

Certified By: (SSWR - Must be a PulteGroup Employee)	Certified By: (Third Party Inspector if required by the Applicable Permit)			
		Mario Alderete		
Site Storm Water Representative - Print Name and Title		Inspector - Print Name		
		Marn Noute		
Site Storm Water Representative Signature (Use Ink)	Date	Inspector Signature (Use Ink)	Date	
VI. Justification for non-completion of Responsive Actions				

Describe why any Responsive Actions were not corrected within the permit required time period (if applicable).

N/A

Attach additional sheet(s) if necessary