

City of Albuquerque Stormwater Construction Site Inspection Report

General information							
Project Name: Aloha RV							
Location:		8212 Pan American Frwy					
Site Contact Name & Agency		Peter Larson/	Shawn B.	ESC File No.	C18E104		
		Aloha RV		NPDES Id. No.	NMR100Z8		
Inspection Date:		02/20/20 St	art/End Time: 0	930/0935hrs			
	water Inspecto		mothy E. Sims				
	ction Phase:	STABILIZED					
Type of I	nspection: x	Regular	Storm Event	Post Storm I	vent >0.25"	311/Complaint	Follow Up
Weath	er at time of i	nspection?	Cle	ar	Tempe	rature: ~	38*
Estimated	l date of last s	torm 0.25" oı	r greater			11/2//2019	
Itom							
Item	Deficiency/ Corrective Action						
Number							
	r						
	CTA DILIZED						
	STABILIZED						
	JIADILIZED						
	L						
2.1	D: 1 (f :: 2	() (())	Nie				
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	tion Reports		Latest rep	oort Date:		
							,
Notes:							
IVULCS.	ļ						
							J

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

02/20/20