

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information												
Project Name:			Aloha RV									
Location:			8212 Pan American Frwy									
Site Contact Name &			Peter Larson		ESC File			C18E104				
Agency			Aloha RV		NPDES I	l. No.		NMR10	NMR100Z8			
Inspection			04/22/19	t/End Time: C	0900/0930	Ohrs						
	water Inspec	ctor	r: Timoth Sims									
Construc	tion Phase:		Demo									
Type of Inspection:			Regular	9	Storm Event	Post S	orm l	Event >0.25"	311/Com	nplaint	x Follov	√Up
Weath	er at time c	of ir	spection?		Cle	ear		Temper	ature: ~	,	63*	:
Estimated	date of las	st st	orm 0.25"	or g	greater			4/17/2019				
Item	Deficiency/Court Addition											
	Deficiency/ Corrective Action											
Number	Dravida NDDES pacting for this site visible from Bight of way											
1	Provide NPDES posting for this site visible from Right-of-way.											
2	provide the ability to cover dumpster.  Provide latest self-inspection reports 04/17/10 a storm event essured.											
3	Provide latest self inspection reports. 04/17/19 a storm event occurred.											
2.1	Discharge off site	e?	(Y/N)		No							
4	Self Insp	ecti	ion Reports	5		Late	st rep	port Date:				
							-	•				
Notes:												
-												

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

04/22/19\_\_\_\_\_