



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Aloha RV				
Location:	8212 Pan American Frwy				
Site Contact Name & Agency	Peter Larson/ Shawn B.	ESC File No.	C18E104		
	Aloha RV	NPDES Id. No.	NMR100Z8		
Inspection Date:	06/18/19	Start/End Time:	1140/1200hrs		
CoA Stormwater Inspector:	Timothy Sims				
Construction Phase:	Interior work site clean up				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	82*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action			
1	Provide latest self inspection reports.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	4/26/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 06/18/19