



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Aloha RV		
Location:	8212 Pan American Frwy		
Site Contact Name & Agency	Peter Larson/ Shawn B.	ESC File No.	C18E104
	Aloha RV	NPDES Id. No.	NMR100Z8
Inspection Date:	08/15/19	Start/End Time:	0925/0930hrs
CoA Stormwater Inspector:	Timothy Sims		
Construction Phase:	Interior work site clean up		
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input type="checkbox"/> 311/Complaint <input checked="" type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	66*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
	all previous issues mitigated, no new issues observed		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 8/2/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 08/15/19