



**City of Albuquerque Stormwater Construction Site Inspection Report**

**General Information**

Project Name:	Aloha RV					
Location:	8212 Pan American Frwy					
Site Contact Name & Agency	Peter Larson/ Shawn B.		ESC File No.	C18E104		
	Aloha RV		NPDES Id. No.	NMR100Z8		
Inspection Date:	11/18/19	Start/End Time:	0900/0915hrs			
CoA Stormwater Inspector:	Timothy Sims					
Construction Phase:	Interior work site clean up					
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	49*
Estimated date of last storm 0.25" or greater	10/4/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 11/8/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:  
 Contact information: Timothy E. Sims - (505) 803-6155  
                                     [tsims@cabq.gov](mailto:tsims@cabq.gov)                                      11/18/19

---