



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Aloha RV				
Location:	8212 Pan American Frwy				
Site Contact Name & Agency	Peter Larson/ Shawn B.	ESC File No.	C18E104		
	Aloha RV	NPDES Id. No.	NMR100Z8		
Inspection Date:	12/18/19	Start/End Time:	0910/0915hrs		
CoA Stormwater Inspector:	Timothy Sims				
Construction Phase:	Interior work site clean up				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	25*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action			
	no issues observed			
	***Please send latest SWPPP self-inspection report			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	11/22/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 12/18/19