



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Aloha RV		
Location:	8212 Pan American Frwy		
Site Contact Name & Agency	Peter Larson/ Shawn B. Aloha RV	ESC File No.	C18E104
		NPDES Id. No.	NMR100Z8
Inspection Date:	12/30/19	Start/End Time:	0920/0925hrs
CoA Stormwater Inspector:	Timothy Sims		
Construction Phase:	Interior work site clean up		
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☒ 311/Complaint ☐ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	25*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed		
	***Please send latest SWPPP self-inspection report		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 11/22/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 12/30/19