

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	C18E				San Pedro Apartments			
NPDES Id. No.	NMR10		ocation:		9320 San Pedro Dr NE			
	5/2024	Owner			Contractor			
Operator		GTA San Pedro) LLC		Tekin Constru			
Contact name & title		Mark Tekin			Carina Sanchez			
e-mail		mark.tekin@tekindevelopment.com			csanchez@tekindevelopment.com			
Contact Ph			505-933-0476					
COA Insp		James Hugh	es		Start/End Time:	10a	m	
Construction Phase:					ticals	·		
						Follow Up		
Weath	er at time of i	inspection?	Rai	n	Temper	ature: ~	45	
Estimated	stimated date of last storm 0.25" or greater 1/4/2024							
Item								
Number	Deficiency/ Corrective Action							
1	None							
2								
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	N/A	Latest re	port Date:	N/A	L .	

Notes:						
Violations were mitigated						

City of Albuquerque Stormwater Inspector Signature and date: Contact information: James Hughes (505-924-3420) jhughes@cabq.gov 1/29/24 James D. Hughes