

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:	Weck's @ 7301 Paseo Del Norte						
Location:	7301 Paseo del Norte						
Site Contact Name &	Tanglewood -Ken		ESC File No.		C19E008		
Agency	kenrupp101@gmail.com		<u> </u>	NPDES Id. No.			
Inspection Date:	03/26/19	Start/End Time:	093	30/1000hrs			
CoA Stormwater Inspec	CoA Stormwater Inspector:		Т	Timothy Sims, Stormwater Inspector			
Present Phase of		grading, verticle and work order					
Construction:							
Type of Inspection: x	Regular	Storm Event		Post Storm I	vent >0.25"	311/Complaint	Follow Up
Weather at time of inspection?					Tempe	erature: ~	53*
Clear							
Has there been a storm event since site was Permitted?							

Clarify amount: ( i.e.. <1/4" to >3/4"):

Inspection				
CGP Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes	
1.5	Post a Notice			
2.2.1	Provide and maintain Natural buffer when Waters of the US <50ft.			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.3	Sediment control along any perimeter			
2.2.4	Minimize sediment track out			

2.2.5	Manage stock piles			
2.2.6	minimize dust			
2.2.10	Protect storm drain inlets			
2.2.10	Protect storm drain inlets			
2.2.11	Minimize erosion of conveyance channels			
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.3.1	Equipment and vehicle fueling			
2.3.2	Equipment and vehicle washing			
2.3.3	Building material storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and domestic wastes			
2.3.3	Construction and domestic wastes			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	

Notes: (City Inspector Use) Items in compliance can be left blank.

Contact information:

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	
Please for	ward me the latest self-inspection report
	City of Albuquerque Stormwater Inspector Signature and date:

tsims@cabq.gov

Timothy Sims, 505-803-6155 or

03/26/19

<sup>&</sup>lt;sup>1</sup> Construction General Permit (CGP)