



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Allergy Clinic				
Location:	7001 Signal Ave				
Site Contact Name & Agency	Taffazul/ Brent	ESC File No.	C19E065		
		NPDES Id. No.	NMR1001R2		
Inspection Date:	05/01/19	Start/End Time:	1015/1100hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:					
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input checked="" type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	61*
Estimated date of last storm 0.25" or greater	4/22/2019		

Item Number	Deficiency/ Corrective Action		
1	provide sediment BMP on the west side of the SAS connection in Signal		
2	Provide track out pad at site entrance or acceptable a sediment BMP		
3	Please provide latest self-inspection report		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	Requested	Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 05/01/19