

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Na	me.	Allergy Clinic						
Location:		7001 Signal Ave						
Site Contact Name &		Taffazul/ Brent		ESC File No.	C19E065			
Agency				NPDES Id. No.	NMR1001R2			
Inspection Date:		510/2019	10/2019 Start/End Time: 1015/1100hrs			I		
CoA Stormwater Inspecto								
Construction Phase:								
Type of Inspection:		Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	x Follow Up	
							40*	
Weath	er at time of i	nspection?	Ra Ra	in	Tempe	rature: ~ 4/22/2019	43*	
Weather at time of inspection?RainTemperature: ~43*Estimated date of last storm 0.25" or greater4/22/2019								
Item	Deficiency/ Corrective Action							
Number	Denetereyy concerve Action							
	Site is to be swept daily, removing note #3 from violation letter. Work order to begin week of							
	05/013/19. no issues							
	05/015/19. 110 155025							
-								
2.1	Discharge off site?	(Y/N)	No					
4				Latest rep	port Date:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155