

City of Albuquerque Stormwater Construction Site Inspection Report

General Information											
Project Nar	ne:	Allergy Clinic									
Location:		7001 Signal Ave									
Site Contact Name &		Taffazul/ Brent		ESC File No.	C19E065						
Agency		,		NPDES Id. No.	NMR1001R2						
Inspection Date:				0850/900hrs							
CoA Storm	water Inspecto	r: Timothy E. Sims									
	ction Phase:	STABILIZED					1				
Type of Ir	nspection: x	Regular	Storm Event	Post Storm	-vent >0.25"	311/Complaint	Follow Up				
Weathe	er at time of i	nspection?	Cle	ear	Tempe	rature: ~	67*				
Estimated	date of last s	torm 0.25"			Tempe	5/11/2019	07				
Item											
	Deficiency/ Corrective Action										
Number											
	STABILIZED										
			JIA	DILIZ							
2.1	Discharge off site?	(Y/N)	No								
4	Self Inspect	tion Reports	;	Latest rep	oort Date:						
,											

Notes:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155