



## City of Albuquerque Stormwater Construction Site Inspection Report

### General Information

Project Name:	Allergy Clinic		
Location:	7001 Signal Ave NE		
Site Contact Name & Agency	Tafazzul / Brent	ESC File No.	C19E065
		NPDES Id. No.	NMR1001R2
Inspection Date:	023/13	Start/End Time:	1020-1045hrs
CoA Stormwater Inspector:	Timothy Sims, Stormwater Inspector		
Present Phase of Construction:	concrete work, utilities		
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input checked="" type="checkbox"/> 311/Complaint <input checked="" type="checkbox"/> Follow Up

Weather at time of inspection?  
Clear

Temperature: ~ 43\*

Has there been a storm event since site was Permitted?

Clarify amount: ( i.e.. <1/4" to >3/4"): yes, >3/4"

### Inspection

CGP Section	BMP / Activity	Maintenance or Corrective Action Required	Location and Notes
1.5	Post a Notice		
2.2.1	Provide and maintain Natural buffer when Waters of the US <50ft.		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.3	Sediment control along any perimeter		
2.2.4	Minimize sediment track out		

2.2.5	Manage stock piles		
2.2.6	minimize dust		
2.2.10	Protect storm drain inlets		
2.2.10	Protect storm drain inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.3.1	Equipment and vehicle fueling		
2.3.2	Equipment and vehicle washing		
2.3.3	Building material storage	x	batts of insulation broken, clean up and store accordingly
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and domestic wastes		
2.3.3	Construction and domestic wastes	x	domestic and construction require clean up
2.3.4	Washing applicators used for paint, stucco, concrete, etc.	x	provide concrete washout/ clean out
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.4	Dewatering		
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports	requested	Latest report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

<sup>1</sup> Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	concrete flat work in progress no washout location provided per approved plan. Site is in need of refuse/ dumpster (with ability to cover when not in use). Superintendent unavailable

City of Albuquerque Stormwater Inspector Signature and date: \_\_\_\_\_  
Contact information: Timothy Sims, 505-803-6155 or 13-Feb  
[tsims@cabq.gov](mailto:tsims@cabq.gov)