

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Nar	ne:	Luna Vita						
Location:		Wilshire & Loui						
Site Contact Name &		Chris Kelsey- Clear Brook ESC File No.			C19E066			
Agency		ckelsey@still	orooke.com	NPDES Id. No.		NMR10028U		
Inspection Date:				35/1000hrs				
CoA Stormwater Inspector: Timothy E. Sims								
Construction Phase: earthwork Type of Inspection: x Regular Storm Event Post Storm Event >0.25"							Talland Up	
Type of it	ispection: <u>x</u>	Regular	Storm Event	Post Storm	event >0.25	311/Complaint	Follow Up	
Weath	er at time of i	nspection?	Clea	r	Temne	rature: ~	81*	
Estimated	date of last s	storm 0.25" or	rm 0.25" or greater			7/7/2019		
	Sate of the state of product							
Item	Deficiency/ Corrective Action							
Number								
1	Please provide latest SWPPP self-inspection report							
2	Track out at the construction entrance requires mitigation. Please sweep and clean daily if							
	required.							
3	Sediment build up at the intersection of Wilshire and Louisiana requires mitigation.							
				1				
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspec	tion Reports	requested	Latest rep	oort Date:	no reports r	eceived	
Notes:	with future v	vork for the ex	ctension of Wils	shire, Please	provide sed	liment BMP's wh	en	
work is conducted in this area								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

<u>tsims@cabq.gov</u> 08/20/19