



# City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:	Luna Vita		
Location:	Wilshire & Louisiana		
Site Contact Name & Agency	Chris Kelsey- Clear Brook <a href="mailto:ckelsey@stillbrooke.com">ckelsey@stillbrooke.com</a>	ESC File No.	C19E066
		NPDES Id. No.	NMR10028U
Inspection Date:	08/28/19	Start/End Time:	1015/1025hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	earthwork		
Type of Inspection:	<input type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25" <input type="checkbox"/> 311/Complaint <input checked="" type="checkbox"/> Follow Up

Weather at time of inspection?	Clear	Temperature: ~	73*
Estimated date of last storm 0.25" or greater	7/7/2019		

Item Number	Deficiency/ Corrective Action		
	all previous issues mitigated, no new issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 8/27/2019

Notes:	with future work for the extension of Wilshire, Please provide sediment BMP's when work is conducted in this area

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Timothy E. Sims - (505) 803-6155  
[tsims@cabq.gov](mailto:tsims@cabq.gov) 08/28/19