

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	C20E	057 Project Name:			Monet Apartments			
NPDES Id. No. NMR10		DO333 Location:			8400 Alameda Blvd. NE			
	/2022	Owner			Contractor			
Operator		Snyder Construction			Dhilliadhara			
Contact name & title		Zack Snyder			Phil Lindborg			
e-mail		zsnyder@snyder-const.com 505-250-8595			phillindborg@comcast.net 505-450-4388			
Contact Phone #								
COA Inspector		Doug Hughes			Start/End Time: 2:25 PM-2:30 PM			
Construction Phase: Type of Inspection:				idle Event >0.25"   311/Complaint   Follow Up				
			Cloud				50	
	er at time of i			цу	3/23/2022	rature: ~	50	
Item Number	Deficiency/ Corrective Action							
1	The review fees were never paid for the ESC Plan application and the NOI has expired. A new NOI and							
_	ESC Plan will have to be approved by the City prior to any land disturbing activity.							
2	This site was never cleared, it has most of the original native vegitation still in place and some small dirt							
	stockpiles (less than 500cy).							
3								
4								
5								
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	tion Reports	Requested	Latest re	port Date:	None o	n file	
<u></u>								
A1 .								
Notes:								
			· · · · · · · · · · · · · · · · · · ·					

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov