

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Desert Ridge Place Unit 3				
Location:	8715 desert Finch NE				
Site Contact Name & Agency	Chris Madrid	ESC File No.	C20E076		
	Abrazo Homes	NPDES Id. No.	NMR100193		
Inspection Date:		Start/End Time:	8:50	9:00	
CoA Stormwater Inspector:	Curtis Cherne				
Construction Phase:					
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☒ Follow Up

Weather at time of inspection?	Cloudy	Temperature: ~	60
Estimated date of last storm 0.25" or greater	5/10/2019		

Item Number	Deficiency/ Corrective Action		
	none		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 5/10/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Curtis Cherne PE, 505-924-3420

ccherne@cabq.gov

01/00/00

Ante a chem