

City of Albuquerque Stormwater Construction Site Inspection Report

		Genera	al Information			
Project Name:	Mark 3S Holly Development					
Location:	9300 Holly Ave. NE					
Site Contact Name &	Xenia Martin		ESC File No.	C20E078		
Agency	Paaru Builders		NPDES Id. No.	NMR1001BW		1
Inspection Date:	03/11/19	Start/End Time:	0900/0930hrs			
CoA Stormwater Inspec	tor:		Timothy Sims, Stormwater Inspector			
Present Phase of	civil with vertical.					
Construction:						
				1		
Type of Inspection:	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	x Follow Up
Weather at time of inspection?			Temperature: ~ 44*		44*	
rain						
Has there been a storm event since site was Permitted?						
Clarify amount: (i.e <1/4" to >3/4"):			yes, >3/4"			
Inspection						
	<u> </u>	Maintonan	.60			

inspection					
	BMP / Activity	Maintenance or Corrective	Location and Notes		
CGP	Bivir / Activity	Action	Location and Notes		
Section		Required			
1.5	Post a Notice				
2.2.1	Provide and maintain Natural buffer when Waters of the US <50ft.				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.3	Sediment control along any perimeter				
2.2.4	Minimize sediment track out				

2.2.5	Manage stock piles			
2.2.6	minimize dust			
2.2.10	Protect storm drain inlets			
2.2.10	Protect storm drain inlets			
2.2.11	Minimize erosion of conveyance channels			
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.3.1	Equipment and vehicle fueling			
2.3.2	Equipment and vehicle washing			
2.3.3	Building material storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and domestic wastes			
2.3.3	Construction and domestic wastes			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site? (Y/N)	n		
4	Self Inspection Reports	requested	Latest report Date:	

Notes: (City Inspector Use) Items in compliance can be left blank.

Contact information:

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	
last inspec	ction on 02/07/19, I requestsed self inspection reports. I have yet to receive them.
,	

City of Albuquerque Stormwater Inspector Signature and date: Timothy Sims, 505-803-6155 or 03/11/19 tsims@cabq.gov

Construction General Permit (CGP)