



Project Name:		Mark 3S Holly Development									
Location:		9300 Holly Ave. NE									
Site Contact Name & Agency	Xenia Martin				ESC File No.		C20E078				
	Paaru Builders				NPDES Id. No.		NMR1001BW				
Inspection Date:		03/18/19		Start/End Time:		1310/1345hrs					
CoA Stormwater Inspector:				Timothy Sims, Stormwater Inspector							
Present Phase of Construction:		civil with vertical.									
		start roadway work									
Type of Inspection:		Regular		Storm Event		Post Storm Event >0.25"		311/Complaint	x	Follow Up	

Temperature: ~ 60*

Clarify amount: (i.e.. $<1/4''$ to $>3/4''$): yes, $>3/4''$

[illegible]

2.2.5	Manage stock piles		
2.2.6	minimize dust		
2.2.10	Protect storm drain inlets		
2.2.10	Protect storm drain inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.3.1	Equipment and vehicle fueling		
2.3.2	Equipment and vehicle washing		
2.3.3	Building material storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and domestic wastes		
2.3.3	Construction and domestic wastes		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.4	Dewatering		
2.1	Discharge off site? (Y/N)	n	
4	Self Inspection Reports	requested	Latest report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

¹ Construction General Permit (CGP)

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	
last inspection on 02/07/19, I requestsd self inspection reports. I have yet to receive them.	

City of Albuquerque Stormwater Inspector Signature and date: _____
Contact information: Timothy Sims, 505-803-6155 or 03/18/19
tsims@cabq.gov