



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Mark 3S Holly Development				
Location:	9300 Holly Ave. NE				
Site Contact Name & Agency	Xenia Martin - Paarug Builders	ESC File No.	C20E078		
	pm@paarugroup.com	NPDES Id. No.	NMR1001BW		
Inspection Date:	06/17/19	Start/End Time:	1430/1435hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	STABILIZED				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Cloudy	Temperature: ~	87*
Estimated date of last storm 0.25" or greater	5/11/2019		

Item Number	Deficiency/ Corrective Action		
	STABILIZED		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 06/17/19