

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Nar	ne:	Holly Senior L	iving / Amaran S	enior Living			
Location:		9100 Holly					
Site Contact Name & Agency		Xenia - Paaru		ESC File No.		C20E079	
		si@paarugro	oup.com	NPDES Id. No.		NMR10025V	
Inspection Date:				840/0900hrs			
CoA Storm	water Inspector	r: T	imothy E. Sims				
Construction Phase: vertical							
Type of Inspection: x Regular Storm Event x Post Storm Event >0.25" 311/Complaint Follow Up							
	er at time of i		Cle	ar	Tempe	rature: ~	51*
Estimated	date of last s	torm 0.25" or greater			4/13/2020		
Item							
	Deficiency/ Corrective Action						
Number							
	all previous issues mitigated, no new issues observed with this inspection.						
	***Due to the pending PNM power installationan understanding with the P.M. and S.I. daily						
	sweeping of trackout to be implemented until trackout pad can be rehabilitated or pavement						
	installation of site preventing trackout.***						
		<u>.</u>					
				_			
2.1	Discharge off site?	(Y/N)	No		-		
4	Self Inspect	ion Reports		Latest rep	ort Date:	4/20/20)20
Notes:							
-							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

04/22/20 _____