

City of Albuquerque Stormwater Construction Site Inspection Report

			General In	formation				
Project Name:		Amarand						
Location:		9100 Holly Ave NE		ESC File No.	C20E079	NPDES Id. No.	NMR10025V	
Site Contact Name &		Xenia - Paaru		Phone: (o)	505-307-1501			
Agency		si@paarugroup.com		Phone: (m)				
Owner		Hemal Patel - Paaru Builders		Phone: (o) 505-271-1288				
Owner's e-mail		hemal@paarugroup.com		Phone: (m)				
Inspection Date:			art/End Time: 12	05/1215hrs				
CoA Stormwater Inspecto		r: Ti	imothy E. Sims					
Construction Phase:				-	tical			
Type of Inspection: x		Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up	
Weath	er at time of i	nspection?	Clea	r	Tempe	erature: ~	86*	
Estimated date of last s		torm 0.25" o	r greater			7/25/2020		
ltem Number	Deficiency/ Corrective Action							
	no issues observed with this inspection.							
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspect	tion Reports		Latest rep	oort Date:	7/27/2	020	

Notes:	inspection conducted practicing safe social distancing

City of Albuquerque Stormwater Inspector Signature and date:Contact information:Timothy E. Sims - (505) 803-6155tsims@cabq.gov07/30/20