



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	C20E079	Project Name:	Holly Senior Living
NPDES Id. No.	NMR10025V	Location:	9100 Holly Avenue
5/3/2021	Owner	Contractor	
Operator	Paaru Builders, LLC.	Paaru Group	
Contact name & title	Hemal Patel	Mike Hart	
e-mail	hemal@paarugroup.com	si@paarugroup.com	
Contact Phone #	505-271-1288	505-410-6578; 505-271-1288	
COA Inspector	Thomas Evans	Start/End Time:	12:55 PM/1:00 PM
Construction Phase:	Stabilization		
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Past Storm Event >0.25" ☐ 311/Complaint ☐ Follow Up
Weather at time of inspection?	cloudy	Temperature:	~ 68
Estimated date of last storm 0.25" or greater	4/28/2021		
Item Number	Deficiency/ Corrective Action		
1	None		
2			
3			
4			
5			
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports		Latest report Date: 3/8/2021

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 05/17/2021