

### **INSPECTION REPORT**

# **GENERAL INFORMATION**

DATE OF INSPECTION:	2/17/2020		
COMPANY NAME:	Paaru		
PROJECT NAME:	Holly Ave Construction		
LOCATION:	9100 Holly Ave NE ,Albuquerque,New Mexico,87122		
TRACKING NO:	NMR100000		
COMPLIANCE EVALUATION:	Marginal		
TYPE OF INSPECTION:	7Day		
START TIME:	8:30 AM		
END TIME:	8:45 AM		
INSPECTOR'S NAME:	Kasey Anderson		
INSPECTOR'S TITLE:	Environmental Inspector		
INSPECTOR'S QUALIFICATIONS:	Storm Water Qualified Person		
INSPECTOR'S CONTACT:	505-280-7766		
PHASE OF CONSTRUCTION:	<ul> <li>Clear and Grub ☐ Excavation ✓ Building (vertical)</li> <li>✓ Rough Grading ✓ Infrastructure ☐ Final Grading</li> <li>☐ Final Stabilization</li> </ul>		
WEATHER INFORMATION			
HAS A STORM EVENT OCCUPRED SINCE THE			

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>
WEATHER AT TIME OF THIS INSPECTION:	Clear	
TEMPERATURE:	48	
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>
ARE ANY DISCHARGES OCCURRING NOW?	Yes	<ul><li>No</li></ul>
ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?	Yes	<ul><li>No</li></ul>

# POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	Inlet Protection	None	Initial Install	Add a BMP over the drop inlet in the NW corner of the site (silt fence or cover and wattle around it)	1	EA	<u>Yes</u>
2	Wattles/Socks/Lo g Roll	Reset	None	Reset wattles and silt fence on NW corner fence.	30	LF	<u>Yes</u>
3	Inlet Protection	Update	None	Curb inlet on south side of building will need a wattle or similar item blocking the back opening of the inlet.	1	EA	<u>Yes</u>

# **GENERAL SITE INSPECTION ITEMS**

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	● Yes ○ No ○ N/A	Yes No	
2	Are steep slope areas not actively being worked properly stabilized?	• Yes ONO N/A	Yes No	Erosion still occurring at the NE and SE slopes. Recommend slowing down the water coming onto the site from the east.
3	Are disturbed areas not actively being worked properly stabilized?	Yes No N/A	Yes No	
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	○Yes ● No ○ N/A	● Yes ○ No	Two inlets need their protection upgraded onsite, and NW perimeter BMPs need to be reset.
5	Are discharge points and receiving waters free of any sediment deposits?	• Yes ONo ON/A	Yes No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	Yes ● No N/A	• Yes No	Recommend a general site trash pickup.
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	• Yes ONo ON/A	Yes No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	● Yes ○ No ○ N/A	○Yes	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	Yes No N/A	Yes No	
10	Are offsite flows entering the construction site?	Yes ● No N/A	Yes No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	Yes ● No N/A	Yes No	
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	Yes No N/A	Yes No	
13	Are non-stormwater discharges properly controlled?	• Yes ONo ON/A	Yes No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	• Yes ONo ON/A	Yes No	
15	Are changes to the SWPPP necessary at this time?	Yes ● No N/A	Yes No	
16	Are dust control measures being properly implemented?	• Yes ONo ON/A	Yes No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	• Yes ONo ON/A	◯Yes	

### **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY: Kasey Anderson DATE: February 17, 2020

SIGNATURE AND AFFILIATION:

### **CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	,	DATE:
SIGNATURE:		