

INSPECTION REPORT

GENERAL INFORMATION

DATE OF INSPECTION:	4/20/2020
COMPANY NAME:	Paaru
PROJECT NAME:	Holly Ave Construction
LOCATION:	9100 Holly Ave NE ,Albuquerque,New Mexico,87122
TRACKING NO:	NMR100000
COMPLIANCE EVALUATION:	Marginal
TYPE OF INSPECTION:	7Day
START TIME:	8:15 AM
END TIME:	8:30 AM
INSPECTOR'S NAME:	Kasey Anderson
INSPECTOR'S TITLE:	Environmental Inspector
INSPECTOR'S QUALIFICATIONS:	Storm Water Qualified Person
INSPECTOR'S CONTACT:	505-280-7766
PHASE OF CONSTRUCTION:	 Clear and Grub ☐ Excavation ✓ Building (vertical) ✓ Rough Grading ✓ Infrastructure ☐ Final Grading ☐ Final Stabilization
WEA	ATHER INFORMATION

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?	Yes	No
WEATHER AT TIME OF THIS INSPECTION:	Clear	
TEMPERATURE:	56	
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	Yes	No
ARE ANY DISCHARGES OCCURRING NOW?	Yes	No
ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?	Yes	No

POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	Debris or Waste	Clean	None	Clean up white powder on the outside of the eastern wall.	1	EA	<u>Yes</u>
2	Sediment	Clean	None	Sweep the tracked out sediment at the northern entrance	1	EA	<u>Yes</u>
3	Inlet Protection	Update	None	Adjust the southern onsite curb inlet to cover grate.	1	EA	<u>Yes</u>

GENERAL SITE INSPECTION ITEMS

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	• Yes • No • N/A	Yes No	
2	Are steep slope areas not actively being worked properly stabilized?	• Yes ONo ON/A	Yes No	
3	Are disturbed areas not actively being worked properly stabilized?	• Yes O No O N/A	○Yes • No	Eastern parking lot scheduled to be finished with curb and landscaping.
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	Yes No N/A	Yes No	
5	Are discharge points and receiving waters free of any sediment deposits?	○ Yes ● No ○ N/A	● Yes ○ No	Sweep the tracked out sediment at the north entrance.
6	Is trash/litter from work areas collected and placed in covered dumpsters?	• Yes ONo ON/A	Yes No	
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	● Yes ○ No ○ N/A	Yes No	
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	● Yes ○ No ○ N/A	Yes No	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	Yes No N/A	• Yes No	Clean up the white powder on the outside of the eastern wall.

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
10	Are offsite flows entering the construction site?	○ Yes ● No ○ N/A	☐ Yes ● No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	○ Yes ● No ○ N/A	☐ Yes	
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	• Yes ONo ON/A	Yes No	
13	Are non-stormwater discharges properly controlled?	• Yes ONo ON/A	Yes No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	○ Yes ● No ○ N/A	● Yes ○ No	Street sweeping, inlet protection adjustment, and white powder clean up are recommended.
15	Are changes to the SWPPP necessary at this time?	○ Yes ● No ○ N/A	◯ Yes	
16	Are dust control measures being properly implemented?	● Yes ○ No ○ N/A	◯ Yes ● No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	○Yes ● No ○ N/A	● Yes ○ No	Update the onsite SWPPP book with inspections from April.

CERTIFICATION AND SIGNATURE BY INSPECTOR

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:	Kasey Anderson	DATE:	April 21, 2020

SIGNATURE AND AFFILIATION:

CERTIFICATION AND SIGNATURE BY PERMITTEE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	,	I	DATE:

SIGNATURE: