

## **INSPECTION REPORT**

# **GENERAL INFORMATION**

DATE OF INSPECTION:	5/18/2020				
COMPANY NAME:	Paaru				
PROJECT NAME:	Holly Ave Construction				
LOCATION:	9100 Holly Ave NE ,Albuquerque,New Mexico,87122				
TRACKING NO:	NMR100000				
COMPLIANCE EVALUATION:	Satisfactory				
TYPE OF INSPECTION:	14Day				
START TIME:	10:00 AM				
END TIME:	10:15 AM				
INSPECTOR'S NAME:	Kasey Anderson				
INSPECTOR'S TITLE:	Environmental Inspector				
INSPECTOR'S QUALIFICATIONS:	Storm Water Qualified Person				
INSPECTOR'S CONTACT:	505-280-7766				
PHASE OF CONSTRUCTION:	<ul> <li>Clear and Grub ☐ Excavation ☑ Building (vertical)</li> <li>☑ Rough Grading ☑ Infrastructure ☐ Final Grading</li> <li>☐ Final Stabilization</li> </ul>				
WEA	WEATHER INFORMATION				

LAST INSPECTION?	Yes	<ul><li>No</li></ul>
WEATHER AT TIME OF THIS INSPECTION:	Clear	
TEMPERATURE:	69	
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	Yes	<ul><li>No</li></ul>
ARE ANY DISCHARGES OCCURRING NOW?	Yes	<ul><li>No</li></ul>
ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?	Yes	<ul><li>No</li></ul>

# POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	SWPPP Plan	None	None	None	0	EA	

### GENERAL SITE INSPECTION ITEMS

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	● Yes ○ No ○ N/A	Yes No	
2	Are steep slope areas not actively being worked properly stabilized?	○Yes ● No ○ N/A	• Yes No	Paaru consulted their project engineer regarding the transformer slopes; "It could be cobbles or medium sized angular stone. A small wall would also be fine if you want to do that."
3	Are disturbed areas not actively being worked properly stabilized?	Yes No N/A	Yes No	
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	● Yes ○ No ○ N/A	• Yes No	The two wattles protecting Holly Ave's curb inlets will need replacing soon. The wattles are almost flat and are starting to get holes in the sock.
5	Are discharge points and receiving waters free of any sediment deposits?	● Yes ○ No ○ N/A	Yes No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	● Yes ○ No ○ N/A	● Yes ○ No	All trash is contained within the project, but a site trash pickup is recommended.
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	Yes No N/A	Yes No	
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	•Yes No N/A	Yes No	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	• Yes No N/A	Yes No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
10	Are offsite flows entering the construction site?	○Yes ● No ○ N/A	◯ Yes ● No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	○Yes ● No ○ N/A	◯ Yes	
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	• Yes ONo ON/A	Yes No	
13	Are non-stormwater discharges properly controlled?	• Yes ONo ON/A	Yes No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	• Yes ONo ON/A	Yes No	
15	Are changes to the SWPPP necessary at this time?	○Yes ● No ○ N/A	◯ Yes	
16	Are dust control measures being properly implemented?	● Yes ○ No ○ N/A	Yes No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	• Yes No N/A	Yes No	

#### **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:	Kasey Anderson	<b>DATE</b> : May 18, 2020
---------------	----------------	----------------------------

They tilly

**SIGNATURE AND AFFILIATION:** 

# **CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	,	The state of the s	DATE:

**SIGNATURE:**