

# **INSPECTION REPORT**

## **GENERAL INFORMATION**

DATE OF INSPECTION:	6/2/2020
COMPANY NAME:	Paaru
PROJECT NAME:	Holly Ave Construction
LOCATION:	9100 Holly Ave NE ,Albuquerque,New Mexico,87122
TRACKING NO:	NMR100000
COMPLIANCE EVALUATION:	Marginal
TYPE OF INSPECTION:	Rain Event
START TIME:	11:15 AM
END TIME:	11:30 AM
INSPECTOR'S NAME:	Kasey Anderson
INSPECTOR'S TITLE:	Environmental Inspector
INSPECTOR'S QUALIFICATIONS:	Storm Water Qualified Person
INSPECTOR'S CONTACT:	505-280-7766
PHASE OF CONSTRUCTION:	<ul> <li>Clear and Grub ✓ Excavation ✓ Building (vertical)</li> <li>✓ Rough Grading ✓ Infrastructure ☐ Final Grading</li> <li>☐ Final Stabilization</li> </ul>
IF RAIN EVENT HOW WAS RAINFALL AMOUNT DETERMINED:	□ Rain Gauge ✓ Other CoCoRaHS
WE/	ATHER INFORMATION

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?

O No Yes

Thunderstorm and light rain IF YES, PROVIDE:

#	STORM DATE	ESTIMATED STORM DURATION (HOURS)	APPROXIMATE PRECIPITATION (INCHES)	
1	6/1/2020	5	0.40	

**WEATHER AT TIME OF THIS INSPECTION:** 

Clear

TEMPERATURE:	75	
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	Yes	○ No
ARE ANY DISCHARGES OCCURRING NOW?	Yes	<ul><li>No</li></ul>
ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?	Yes	<ul><li>No</li></ul>

# POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	Inlet Protection	None	Replace	Replace the 2 wattles protecting the curb inlets just north of the project.		EA	<u>Yes</u>
2	Sediment	Clean	None	Sweep sediment on north sidewalk. Recommend resetting wattles near the sediment leak.	1	EA	<u>Yes</u>
3	Inlet Protection	None	Replace	Replace stormwater filter on drain in the SE section of the site.	1	EA	<u>Yes</u>

# **GENERAL SITE INSPECTION ITEMS**

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	● Yes ○ No ○ N/A	Yes No	
2	Are steep slope areas not actively being worked properly stabilized?	● Yes ○ No ○ N/A	Yes No	This last storm has eroded a little more of the NE and SE slopes. Recommend finishing the NE curb and adding a temporary curb to the SE entrance.
3	Are disturbed areas not actively being worked properly stabilized?	● Yes ○ No ○ N/A	Yes No	
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	Yes No N/A	Yes No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
5	Are discharge points and receiving waters free of any sediment deposits?	○Yes ● No ○ N/A	● Yes ○ No	Replace stormwater filter on drain in the SE section of the site. Replace the 2 wattles protecting the curb inlets just north of the project. Sweep sediment on north sidewalk. Recommend resetting wattles near the sediment leak.
6	Is trash/litter from work areas collected and placed in covered dumpsters?	• Yes • No • N/A	Yes • No	Dumpster is overfilled, but is being replaced today.
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	• Yes O No O N/A	Yes No	
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	• Yes O No O N/A	Yes No	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	• Yes ONO ON/A	Yes No	
10	Are offsite flows entering the construction site?	• Yes O No O N/A	Yes No	This last storm has eroded a little more of the NE and SE slopes. Recommend finishing the NE curb and adding a temporary curb to the SE entrance.
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	Yes No N/A	Yes No	
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	• Yes ONO N/A	Yes No	
13	Are non-stormwater discharges properly controlled?	• Yes ONO ON/A	Yes No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	○Yes ● No ○ N/A	● Yes ○ No	Replace stormwater filter on drain in the SE section of the site. Replace the 2 wattles protecting the curb inlets just north of the project. Sweep sediment on north sidewalk. Recommend resetting wattles near the sediment leak.
15	Are changes to the SWPPP necessary at this time?	Yes No N/A	Yes • No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
16	Are dust control measures being properly implemented?	• Yes O No O N/A	Yes No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	● Yes ○ No ○ N/A	◯ Yes	

### **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY: Kasey Anderson DATE: June 02, 2020

Thy Ally

**SIGNATURE AND AFFILIATION:** 

## **CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

**SIGNATURE:**