

INSPECTION REPORT**GENERAL INFORMATION**

DATE OF INSPECTION: 2/8/2021

COMPANY NAME: Paaru

PROJECT NAME: Holly Ave Construction

LOCATION: 9100 Holly Ave NE ,Albuquerque,New Mexico,87122

TRACKING NO: NMR100000

COMPLIANCE EVALUATION: Marginal

TYPE OF INSPECTION: 14Day

START TIME: 8:30 AM

END TIME: 8:45 AM

INSPECTOR'S NAME: Kasey Anderson

INSPECTOR'S TITLE: Environmental Inspector

INSPECTOR'S QUALIFICATIONS: Storm Water Qualified Person

INSPECTOR'S CONTACT: 505-280-7766

PHASE OF CONSTRUCTION: ☐ Clear and Grub ☐ Excavation ☐ Building (vertical)
☐ Rough Grading ☒ Infrastructure ☒ Final Grading
☐ Final Stabilization

WEATHER INFORMATION

HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION? ☐ Yes ☒ No

WEATHER AT TIME OF THIS INSPECTION: Clear

TEMPERATURE: 45

HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION? ☐ Yes ☒ No

ARE ANY DISCHARGES OCCURRING NOW? ☐ Yes ☒ No

ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT? ☐ Yes ☒ No

POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	PHOTO
1	Soil Stabilizer	Update	None	S courtyard, SE corner slope, E courtyard, NE corner area, and E parking lot buffer have not achieved final stabilization yet.	5	EA	Yes
	Soil Stabilizer	Update	None	S courtyard, SE corner slope, E courtyard, NE corner area, and E parking lot buffer have not achieved final stabilization yet.	5	EA	Yes
	Soil Stabilizer	Update	None	S courtyard, SE corner slope, E courtyard, NE corner area, and E parking lot buffer have not achieved final stabilization yet.	5	EA	Yes
	Soil Stabilizer	Update	None	S courtyard, SE corner slope, E courtyard, NE corner area, and E parking lot buffer have not achieved final stabilization yet.	5	EA	Yes
	Soil Stabilizer	Update	None	S courtyard, SE corner slope, E courtyard, NE corner area, and E parking lot buffer have not achieved final stabilization yet.	5	EA	Yes

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	PHOTO
2	Debris or Waste	Clean	None	Clean up the wood debris and sediment gathered on the southern curb of Holly Ave, and clean-out the bottom of the southern inlets.	3	EA	Yes
	Debris or Waste	Clean	None	Clean up the wood debris and sediment gathered on the southern curb of Holly Ave, and clean-out the bottom of the southern inlets.	3	EA	Yes
3	Inlet Protection	None	Replace	Replace inlet protections around Holly ave southern inlets and the inlet to the south of the building.	3	EA	Yes
	Inlet Protection	None	Replace	Replace inlet protections around Holly ave southern inlets and the inlet to the south of the building.	3	EA	Yes
4	Debris or Waste	Clean	None	Remove old BMP debris from the SW corner of the site, and the northern curb inlets on Holly Ave.	3	EA	Yes
	Debris or Waste	Clean	None	Remove old BMP debris from the SW corner of the site, and the northern curb inlets on Holly Ave.	3	EA	Yes

GENERAL SITE INSPECTION ITEMS

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
2	Are steep slope areas not actively being worked properly stabilized?	☐ Yes ☒ No ☐ N/A	☒ Yes ☐ No	S courtyard, SE corner slope, E courtyard, NE corner area, and E parking lot buffer have not achieved final stabilization yet.
3	Are disturbed areas not actively being worked properly stabilized?	☐ Yes ☒ No ☐ N/A	☒ Yes ☐ No	S courtyard, SE corner slope, E courtyard, NE corner area, and E parking lot buffer have not achieved final stabilization yet.
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	☐ Yes ☒ No ☐ N/A	☒ Yes ☐ No	Replace inlet protections around Holly ave southern inlets and the inlet to the south of the building.
5	Are discharge points and receiving waters free of any sediment deposits?	☐ Yes ☒ No ☐ N/A	☒ Yes ☐ No	Clean up the wood debris and sediment gathered on the southern curb of Holly Ave, and clean-out the bottom of the southern inlets.
6	Is trash/litter from work areas collected and placed in covered dumpsters?	☐ Yes ☒ No ☐ N/A	☒ Yes ☐ No	Remove old BMP debris from the SW corner of the site, and the northern curb inlets on Holly Ave.
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	
9	Are materials that are potential stormwater contaminants stored inside or in containers?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	
10	Are offsite flows entering the construction site?	☐ Yes ☒ No ☐ N/A	☐ Yes ☒ No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	☐ Yes ☒ No ☐ N/A	☐ Yes ☒ No	
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	
13	Are non-stormwater discharges properly controlled?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	☐ Yes ☒ No ☐ N/A	☒ Yes ☐ No	The site has not been fully stabilized; a lot of the eastern side of the project and part of the eastern parking lot area. We also recommend cleaning the Holly Ave southern curb and inlets. We recommend inlet protections be replaced until site is fully stabilized.
15	Are changes to the SWPPP necessary at this time?	☐ Yes ☒ No ☐ N/A	☐ Yes ☒ No	
16	Are dust control measures being properly implemented?	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	☒ Yes ☐ No ☐ N/A	☐ Yes ☒ No	We are still in discussion with Paaru builders for this report to count as the final SWPPP inspection.

CERTIFICATION AND SIGNATURE BY INSPECTOR

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY:

Kasey Anderson

DATE:

February 09, 2021

SIGNATURE AND AFFILIATION:



CERTIFICATION AND SIGNATURE BY PERMITTEE

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:

DATE:

SIGNATURE: