

## **INSPECTION REPORT**

# **GENERAL INFORMATION**

DATE OF INSPECTION:	7/15/2019		
COMPANY NAME:	Paaru		
PROJECT NAME:	Holly Ave Construction		
LOCATION:	9100 Holly Ave NE ,Albuquerque,New Mexico,87122		
TRACKING NO:	NMR100000		
COMPLIANCE EVALUATION:	Marginal		
TYPE OF INSPECTION:	7Day		
START TIME:	12:15 PM		
END TIME:	12:45 PM		
INSPECTOR'S NAME:	Kasey Anderson		
INSPECTOR'S TITLE:	Environmental Inspector		
INSPECTOR'S QUALIFICATIONS:	Storm Water Qualified Person		
INSPECTOR'S CONTACT:	505-280-7766		
PHASE OF CONSTRUCTION:	<ul> <li>Clear and Grub ✓ Excavation ☐ Building (vertical)</li> <li>Rough Grading ☐ Infrastructure ☐ Final Grading</li> <li>Final Stabilization</li> </ul>		
WE	ATHER INFORMATION		
HAS A STORM EVENT OCCURRED SINCE THE LAST INSPECTION?	○ Yes		
WEATHER AT TIME OF THIS INSPECTION:	Clear		
TEMPERATURE:	88		
HAVE ANY DISCHARGES OCCURRED SINCE THE LAST INSPECTION?	○ Yes		
ARE ANY DISCHARGES OCCURRING NOW?	○ Yes ● No		
ARE ANY PORTIONS OF YOUR SITE UNSAFE TO INSPECT?	○ Yes		

## POLLUTION PREVENTION, SEDIMENT AND EROSION CONTROL BMP'S

#	S&E/P2 CONTROLS	MAINTENANCE	CORRECTIVE ACTION	LOCATION	QUANTITY	UNIT	РНОТО
1	Construction Entrance	None	Upgrade	Upgrade rocks at NW construction entrance	1	EA	
2	Sediment Track Out	Clean	None	SE construction entrance	1	EA	
3	Sediment Track Out	Clean	None	NW const. ent. and sidewalk	1	EA	
4	Silt Fence	None	Repair	NE corner silt fence on construction fence	40	LF	
5	Silt Fence	None	Repair	S silt fence conc. curb	5	LF	
6	Silt Fence	None	Repair	NW silt fence damage	5	LF	

# **GENERAL SITE INSPECTION ITEMS**

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
1	Is the SWPPP signage clearly posted with the correct information and properly displayed at an obvious perimeter location?	●Yes ○No ○N/A	● Yes ○ No	SWPPP sign delivery on next visit.
2	Are steep slope areas not actively being worked properly stabilized?	• Yes ONo ON/A	Yes No	
3	Are disturbed areas not actively being worked properly stabilized?	• Yes ONo ON/A	Yes No	
4	Are natural resource areas (e.g. streams, wetlands, mature trees, etc.) protected with barriers or similar BMPs?	• Yes ONo ON/A	Yes No	
5	Are discharge points and receiving waters free of any sediment deposits?	• Yes ONo ON/A	Yes No	
6	Is trash/litter from work areas collected and placed in covered dumpsters?	• Yes ONo ON/A	Yes No	
7	Are washout facilities (e.g. paint, stucco, concrete) available, clearly marked and maintained?	• Yes ONo ON/A	Yes No	
8	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks or any other deleterious material?	• Yes ONO ON/A	Yes No	

#	INSPECTION ITEM	INSPECTOR'S OBSERVATION	ACTION REQUIRED?	NOTES
9	Are materials that are potential stormwater contaminants stored inside or in containers?	• Yes • No • N/A	◯ Yes	
10	Are offsite flows entering the construction site?	Yes No N/A	○Yes ● No	
11	Is there any evidence that pollutants are leaving the site or are not properly contained on site?	Yes No N/A	◯ Yes	
12	Are traffic and parking areas restricted so as to reduce soil erosion and dust?	Yes No N/A	Yes No	
13	Are non-stormwater discharges properly controlled?	• Yes No N/A	○Yes ● No	
14	Is the project being operated in compliance with the SWPPP and with permit conditions at this time?	• Yes • No • N/A	◯ Yes	
15	Are changes to the SWPPP necessary at this time?	○Yes ● No ○ N/A	◯ Yes ● No	
16	Are dust control measures being properly implemented?	● Yes ○ No ○ N/A	● Yes ○ No	Make sure to post the Fugitive Dust Control Permit required for City of Albuquerque. Also, having stockpiles higher than 14ft is not in compliance with the fugitive dust control permit.
17	Are the SWPPP documentation and records up to date and accurately reflect the current conditions? (e.g. Site Map, Inspection Reports, Installation Dates)	• Yes No N/A	Yes No	

## **CERTIFICATION AND SIGNATURE BY INSPECTOR**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

INSPECTED BY: Kasey Anderson DATE: July 15, 2019

Thy Ally

**SIGNATURE AND AFFILIATION:** 

## **CERTIFICATION AND SIGNATURE BY PERMITTEE**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

PRINT NAME AND TITLE:	,	DATE:
SIGNATURE:		