



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Swim Lab				
Location:	8120 Ventura				
Site Contact Name & Agency	Joe - Klinger joea@klingerllc.com	ESC File No.	C20E082		
		NPDES Id. No.	NMR10028F		
Inspection Date:	01/27/20	Start/End Time:	1230/1250hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	vertical				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Cloudy	Temperature: ~	47*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date: 1/24/2020

Notes:	Entrance is swept daily/ as needed for track out.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 01/27/20