City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Swim Lab						
Location:	8120 Ventura						
Site Contact Name & Agency	Joe - Klinger			ESC File No.	C20E082		
	joea@klingerllc.com			NPDES Id. No.	NMR10028F		
Inspection Date:	02/27/20	Start/End Time:	1015/1030hrs				
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:	STABILIZED						
Type of Inspection:	x Regular	Storm Event		Post Storm Event >0.25"		311/Complaint	Follow Up

Weather at time of inspection?	Clear	Temperature: ~	47*
Estimated date of last storm 0.25" or greater			

Item Number	Deficiency/ Corrective Action			
	STABILIZED			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports		Latest report Date:	

Notes:	

City of Albuquerque Stormwater Inspector Signature and date: Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ou=Planning, email=tsims@cabq.gov, c=US
Date: 2020.02.28 09:27:48 -07'00'

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov 02/27/20