

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Nar	ne:	Swim Lab						
Location:		8120 Ventura	ì					
Site Contact Name & Agency		Jason - Klinge		ESC File No.		C20E082		
			asont@klingerllc.com NPDES Id. No.			NMR10028F		
Inspection Date:			start/End Time:	0935/0945				
CoA Storm	vater Inspecto	r: T	imothy E. Sims					
	tion Phase:				nwork		_	
Type of In	spection: x	Regular	Storm Event	Post Storm I	vent >0.25"	311/Complaint	Follow Up	
							G 2-1	
Weath	er at time of i	nspection?	Cle	ar	Tempei	rature: ~	64*	
Estimated	date of last s	torm 0.25" o	r greater		10/4/2019			
Item			Deficien	/ C				
Number	Deficiency/ Corrective Action							
Nullibei	no issues observed.							
	110 133463 0836							
			<u>, </u>	T				
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspect	ion Reports		Latest rep	oort Date:	10/4/20)19	
Notes:	Entrance is sy	wept daily/ a	s needed for tr	ack out.				
•								

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

10/09/19_____