



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Fanning Orthodontics				
Location:	8120 Ventura				
Site Contact Name & Agency	Michael Fanning - Lemrik	ESC File No.	C20E084		
	mikefanningirish@yahoo.com	NPDES Id. No.	NMR1002PM		
Inspection Date:	01/27/20	Start/End Time:	1230/1250hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	foundations				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Cloudy	Temperature: ~	47*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action		
1	Please provide the NPDES posting for this site.		
2	Please provide the latest SWPPP self-inspection for this site.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requestes	Latest report Date: not on file

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 01/27/20