



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Fanning Orthodontics		
Location:	8120 Ventura		
Site Contact Name & Agency	Michael Fanning - Lemrik mikefanningirish@yahoo.com	ESC File No.	C20E084
		NPDES Id. No.	NMR1002PM
Inspection Date:	02/04/20	Start/End Time:	1140/1220hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	foundations		
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☐ 311/Complaint ☒ Follow Up

Weather at time of inspection?	Snow	Temperature: ~	47*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action		
	all previous issues resolved, no new issues observed		
	***Please provide latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: not on file

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 02/04/20