



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Fanning Orthodontics				
Location:	8120 Ventura				
Site Contact Name & Agency	Michael Fanning - Lemrik	ESC File No.	C20E084		
	mikefanningirish@yahoo.com	NPDES Id. No.	NMR1002PM		
Inspection Date:	03/20/20	Start/End Time:	0840/0850hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	foundations				
Type of Inspection:	☒ Regular	☐ Storm Event	☐ Post Storm Event >0.25"	☐ 311/Complaint	☐ Follow Up

Weather at time of inspection?	Cloudy	Temperature: ~	39*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action		
	no issues observed with this inspection		
	***Please provide latest SWPPP self-inspection report.		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: 1/24/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 03/20/20