
PROPRIETARY COMPANY MATERIAL



PulteGroup

Date & Time : 03-16-2020 at 11:51 AM

				Coloup							
NATIONAL STORM WATER QUALITY PROGRAM SITE INSPECTION REPORT (SIR)											
			For use on most PulteGr	oup Sites as of 01/01/2016							
Community Name: PulteGroup-MS-1026:Montecito Vistas, Vista Vieja, Albuquerque, NM 87120 NPDES: NMR1000BZ											
	(Include Site Name, City, State, Zip Code and NPDES/Construction Storm Water Permit Number)										
Master Si	ite List ID:	932	Insp	ection performed by: <u>Tim Slat</u>	unas, CESSWI CISEC, Green O	Globe					
				(Print Na	ame, Company, and Title / Qua	lifications)					
Stages of Construction: (ch		(check all that apply)	Land Development	Inactive	Vertical Construction	Post-Construction					
0			Land and Vertical								
Type of Inspection: (cl		(check all that apply)	Routine Inspection	Storm-Event Related	Final Site Inspection						
Type of I	iispection.	(check all that apply)		Storm-Event Related	Final Site inspection						
			Other:								
I.	I. SWPPP - Respond to all Questions										
<u>Item</u>											
А	Was the SWPPP access	ible at the time of the inspect	ion?		\boxtimes	If "No," then an Action Item is required.					
В	Is the SSWR correctly i	dentified in the SWPPP?			\boxtimes						
С	Does the SWPPP reflec	t the current stage of develop	ment?		\boxtimes	Describe all Action Items					
D	Was the SWPPP accessible at the time of the inspection? If "No," then an Activity is the an Activity is the SSWR correctly identified in the SWPP? Is the SSWR correctly identified in the SWPP? Image: Correctly identified in the SWPP? Does the SWPPP reflect the current stage of development? Image: Correctly identified on the preceding reports been resolved? Have all SIR action Items identified on the preceding reports been resolved? Image: Correctly identified on the preceding reports been resolved? Is NSQP Signage posted and in compliance with NSQP requirements? Image: Correctly identified on the preceding reports been resolved?										
Е	Is NSQP Signage poste	ed and in compliance with NS	SQP requirements?		\boxtimes						
II.	Estimated date of mo	ost recent Storm Event Th	at triggered an Inspection: <u>11-2</u>	1-2019							
	Provide rainfall inform	ation as required by the App	licable Permit: <u>.75 Inches</u>			e storm-event related Inspection required by the Applicable Permit)					
III.	Site BMP Inspection	L	Not		riequency	required by the Applicable relinit)					
Item	SWPPP Items		Applicable	Acceptable	Action Item	Assigned To					
	Control					<u></u> 8					
1	Protection of Disturbed	d A roac									
2	Slope Protection	I Altas									
3	Vegetation / Revegetati	ion									
4		vices / Outlet Protection		\square							
-	-	vices / Outlet Fiotection									
	nt Control		_		-						
5	Check Dams (rock, grav	vel, other)	님		<u></u>						
6	Silt Fence				<u></u>						
7	Berms, Dikes, Straw W				<u></u>						
8	Detention Basins/Sedin	-	님		<u></u>						
9	Stockpiles Protected/St				·						
10	Storm Water Inlet Prote			Ä	LJ .						
Housek	eeping / Trade Compl	iance									
11	Waste and Trash Manaş	gement				Pulte					
12	Spill and Leak Prevent	ion	\square	\boxtimes							
13	Sanitary Stations			\boxtimes							
14	Concrete and Construct	tion Washouts			\boxtimes	Pulte					
15	Material Use and Poten	tial Contaminate Storage		\boxtimes							
16	Equipment Storage and	-	Ē								
17	Construction Exits and		Ē	$\overline{\mathbf{X}}$							
18	Dust Control		Ē	$\overline{\mathbf{X}}$							
					· ·						
19	Street Sweeping		\Box		\boxtimes	Pulte					

PROPRIETARY COMPANY MATERIAL

		Not					
<u>Item</u>	<u>SWPPP Items (continued)</u>	<u>Applicable</u>	<u>Acceptable</u>	Action Item	<u>Assign</u>	<u>ed To</u>	
Other			_	_			
20	Non-Storm Water Flow						
21	Site's Weathering of Storm Events	\mathbf{X}					
22	Site Discharge Points		\boxtimes				
23	BMP Provider Performance		\boxtimes				
24	Cut Back Curb		\boxtimes	\boxtimes	Pul	Pulte	
IV.	Action Items			V. Responsive Action	Completion		
Item	Location and Responsive Action to be taken			Date Noted	Date of Completion	Initials	
11	Deficiency Name: 9112 Vista Dibujo Corrective Action: Need to contain the construction o	debris on the lot		03-16-2020			
19	Deficiency Name: 9132 Vista Bosquejo Corrective Action: Need to sweep in front of the lot			03-16-2020			
19	Deficiency Name: Piedra Aspero Corrective Action: Need to sweep the street		03-16-2020				
19	Deficiency Name: Piedra Dibujo Corrective Action: Need to sweep the street			03-16-2020			
24	Deficiency Name: 9104 Piedra Dibujo Corrective Action: Need to cut back the curb			03-16-2020			
24	Deficiency Name: 9119 Retablo Corrective Action: Need to cut back the curb			03-16-2020			

Attach additional sheet(s) of SIR addendum if necessary

SIR must be reviewed and signed below by SSWR - Not Delegable: I certify under penalty of law that Sections I-V of this document and all attachments were prepared by me or under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. In the event there are no Action Items in this report that have remained unresolved for a period in excess of that allowed by the Applicable Construction General Permit, I further certify under penalty of law that this Site is in compliance with the SWPPP and the Applicable Construction General Permit. I am aware that there are significant penalties for submitting false information including the possibility of fine and imprisonment for knowing violations. Certification applies to the area under the supervision of the SSWR

Certified By: (SSWR - Must be a PulteGroup Employee)	Certified By: (Third Party Inspector if required by the Applicable Permit)		
Chris Keeland	Tim Slatunas		
Site Storm Water Representative - Print Name and Title	Inspector - Print Name		
		AMMA	
Site Storm Water Representative Signature (Use Ink)	Date	Inspector Signature (Use Ink)	Date

VI. Justification for non-completion of Responsive Actions

Describe why any Responsive Actions were not corrected within the permit required time period (if applicable).

N/A

Attach additional sheet(s) if necessary