

# CITY OF ALBUQUERQUE



June 5, 2018

Bob Prewitt, DR Scott LLC, [prewitt@swcp.com](mailto:prewitt@swcp.com)

Carlos Spiess, Sundance Mechanical and Utility Corp., [carlos@sundancemech.com](mailto:carlos@sundancemech.com)

Site: La Cuentista Unit 2

**Re: Drainage Ordinance (14-5-2-1) Violations for Erosion and Sediment Control**

Dear Mr. Prewitt,

The following violations were observed at today's inspection.

1. There was sediment in the south gutter on Rosa Parks Rd.
2. A dirt ramp was built in Rosa Parks Rd to facilitate transporting material across the roadway.
3. There was no vehicle tracking control for vehicles transporting material across Rosa Parks Rd. The dirt on the south side of Rosa Parks Rd was on the concrete apron in flow-line of the gutter.
4. Workers are exiting the site at Red Root St. There is no vehicle tracking control.
5. A sediment BMP (e.g. rock bags or mulch sock) is required on the concrete apron at Red Root St.
6. Self-inspection reports were not provided upon request.

PO Box 1293

Albuquerque

NM 87103

[www.cabq.gov](http://www.cabq.gov)

Photos are shown below:



Dirt ramp in Rosa Parks Rd.



# CITY OF ALBUQUERQUE



No Vehicle Tracking Control onto Rosa Parks Rd. Dirt on concrete apron of roadway.

PO Box 1293

Albuquerque

NM 87103

[www.cabq.gov](http://www.cabq.gov)



Truck transporting material from site across Rosa Parks Rd.



# CITY OF ALBUQUERQUE



PO Box 1293

Sediment in gutter in Rosa Parks Rd.

Albuquerque

NM 87103

[www.cabq.gov](http://www.cabq.gov)





# CITY OF ALBUQUERQUE



No sediment BMP and no Vehicle Tracking Control on Red Root St.



PO Box 1293

No sediment BMP.

Albuquerque

NM 87103

[www.cabq.gov](http://www.cabq.gov)

**Required Mitigation:**

1. Remove sediment from the south gutter on Rosa Parks East of the high point (approximately mid-site) and prevent from occurring in the future. Silt fence or similar may be necessary to prevent sediment from entering the roadway.
2. Remove the dirt ramp from Rosa Parks Rd to facilitate transporting material across the roadway and do not construct dirt ramps in the future. Cold-mix asphalt is an acceptable material for a ramp.
3. Provide vehicle tracking control for vehicles transporting material across Rosa Parks Rd. Remove sediment from concrete apron on the south side of Rosa Parks Rd.
4. Provide vehicle tracking control for the exit on Red Root St.
5. Provide an acceptable sediment BMP at Red Root St. Sediment BMP is to seal on the concrete. Rock bags or mulch socks may work, but must be adequately supported.
6. Provide self-inspection reports from 5-1-18 to 6-4-18.

PO Box 1293

Per the previous Violation letter, the City is assessing a fine of \$500. This fine is for one day.

Albuquerque

Additional days may be added if the violations are not mitigated upon a follow-up inspection in ten days. In addition, your non-compliance may be reported to the New Mexico Environment Department, Surface Water Quality Bureau to aid in the determination if this issue is to be forwarded to the EPA.

NM 87103

If you have any questions, you can contact me at 924-3420.

Sincerely,

Curtis Cherne, P.E.  
Principal Engineer, Stormwater Quality  
Planning Dept.

[www.cabq.gov](http://www.cabq.gov)