

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	D10E002D		oject Name:	La Cuentiasta III & Stockpile			
NPDES Id. No.			cation:		Rosa Parks and Kimmick		
8/9/2022		Owner		Contractor			
Operator		Pulte Homes of NM			Guzman Construction		
Contact name & title					Rudy Guzman		
e-mail		Kevin.Patton@PulteGroup.com			rudy@guzmancs.com		
Contact Phone #		505-341-8591			505-459-3128		
COA Inspector		Doug Hughes			Start/End Time: 1:15 PM		
Construction Phase:					aging		
Type of Inspection:		Regular	Storm Event	Past Storm	Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection? Clear Temperature: ~ 96							
Estimated date of last storm 0.25" or greater 7/24/2022							
Item Number	Deficiency/ Corrective Action						
1	A separate SWPPP and NOIs were approved by the City for the Rosa Parks Stockpile Yard (see file						
1	C11E004 and NMR1004ZB, NMR100501 and NMR100504)						
2	Current self-inspection reports were missing from the onsite SWPPP for La Cuentista III.						
3							
4							
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspec	tion Reports	Requested	Latest re	port Date:	7/7/20	22
Notes:							
The SWPPP is in the lockbox on Pulte's posting sign at the SW corner of the site.							

City of Albuquerque Stormwater Inspector Signature and date: 8/11/2022

Contact information: Doug Hughes (505-924-3420)

jhughes@cabq.gov

James D. Hughes