

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:		7901 Las Lomitas					
Location:		7901 Las Lomitas					
Site Contact Name & Agency		Joshua Pineda - joshua.pineda@comcast.net		ESC File No.		D16E002i	
		Las Lomitas Industyrial		NPDES Id. No.		NMR1002E4	
Inspection Date:		06/24/20	Start/End Time:	0750/0800hrs			
CoA Stormwater Inspector:			Timothy E. Sims				
Construction Phase:		vertical					
Type of Inspection:	x	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	73*
Estimated date of last storm 0.25" or greater	6/1/2020		

Item Number	Deficiency/ Corrective Action			
	no new issues observed with this inspection			
	***Please provide latest SWPPP self-inspection report			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	5/20/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 06/24/20