

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:		7901 Las Lomitas					
Location:		7901 Las Lomitas					
Site Contact Name & Agency	Joshua Pineda			ESC File No.	D16E002I		
	Joshua Pineda - joshua.pineda@comcast.net			NPDES Id. No.	NMR1002E4		
Inspection Date:	08/17/20	Start/End Time:	0950/0955hrs				
CoA Stormwater Inspector:		Timothy E. Sims					
Construction Phase:		STABILIZED					
Type of Inspection:	x	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up	

Weather at time of inspection?	Clear	Temperature: ~	82*
Estimated date of last storm 0.25" or greater	7/25/2020		

Item Number	Deficiency/ Corrective Action		
	STABILIZED		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes:	inspection conducted adhering to Covid-19 constraints

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 08/17/20