



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	7901 Las Lomas		
Location:	7901 Las Lomas		
Site Contact Name & Agency	Joshua Pineda - joshua.pineda@comcast.net	ESC File No.	D16E002i
	Las Lomas Industrial	NPDES Id. No.	NMR1002E4
Inspection Date:	12/11/19	Start/End Time:	0750/0810hrs
CoA Stormwater Inspector:	Timothy E. Sims		
Construction Phase:	utilities		
Type of Inspection:	☐ Regular	☐ Storm Event	☐ Post Storm Event >0.25" ☒ 311/Complaint ☒ Follow Up

Weather at time of inspection?	Clear	Temperature: ~	30*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action		
	all issues mitigated, no new issues observed with this inspection		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports	requested	Latest report Date: not on file

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 12/11/19